




Formers and ribs were drawn from wood pattern and amended where slots and notches were not aligned as should be.

This drawing has been verified by construction.



Join L5a to L5b at stepped joint