




FLYING MODEL PROP
BLOCK $7 \times 1\frac{3}{8} \times 1\frac{3}{16}$

ROUND TIPS ON
BROKEN LINES AFTER
CARVING






SCALE PROP.

LAMINATE TWO FRONT
COWLING FORMERS BE-
FORE SHAPING



M- STIFF PAPER
OR VENEER
N- SHEET Balsa BRACE
MAKE 8
O- FRONT FORMERS
P- REAR FORMER



COWLING FORMERS

PLATE-5